

JAN 14 2002

DIVISION OF OIL, GAS AND MINING

STATE OF UTAH DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

1594 West North Temple - Suite 1210 Box 145801 Salt Lake City, Utah 84114-5801 Telephone: (801) 538-5291 Fax: (801) 359-3940

ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

Genera	al Information
1.	Report Time Period: From (mo./yr.) JAN 2001 To (mo./yr.) DEC 2001
2.	DOGM File Number (Mine No): M /045/002
3.	Mine Name: REILLY WENDOVER
4.	Mineral(s) Mined (or permitted to mine): POTASH
5.	Type of mine ✓ Surface Mine or Underground Mine
6.	Legal Description (Location of Lands Affected):
	1/4,1/4,1/4, Section, Township, Range
	1/4,1/4,1/4, Section, Township, Range
	1/4,1/4,1/4, Section, Township, Range
Name	of Operator or Company: REILLY WENDOVER
8.	Permanent Street Address: Z'Z MILES EAST FRONTAGE ROAD
	City, State, Zip: WENDOVER, UT 84083 - 0580
	Phone: 435/665-2241 Fax: 435/665-2561
9.	Company Representative (or designated operator):
	Name: GREGORY M. Foy
	Title: PLANT MANAGER
	Business Address: P. O. Box 580
	City, State, Zip: WENDOVER, UT 84083 - 0580
	Phone: 435/665-2241 Fax: 435/665-2561
	Please check if any of the above information has changed since previous year.
<u>Minin</u>	g and Reclamation
1.	Was there any mine related activity during the past year? Yes ☒ No □
2.	If no - what was the last year of activity?
3.	If yes - how much ore or mineral was mined? 154, 218 ST

٦.	additional surface disturbances that occurred during the past year.
	Cleaned approximately 80,000 feet of channel/dike.
	Reclaimed approximately 10,560 feet of channel/dike.
5.	How much additional acreage was disturbed during the past year?
6.	How much acreage was reclaimed during the past year?24.2
7.	Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.
	Reclaimed approximately 10,560 feet of channel/dike.
	Used excavator to fill in channels with dike spoils.
	Used dozer to smooth out surface (grading). Evaluation was based on internal visual inspection.
8.	What is the total disturbed acreage of entire project at years end? 410.2
9.	Briefly summarize any mining and/or reclamation plans for the upcoming year.
	The mine is scheduled to be operational during 2002,
	except for a 6 month shutdown due to a poor harvest.
	Collection ditches will continue to be cleaned, with plans
	to complete new collection ditches as outlined in the mining plan for Pond System II.
NOTE:	Section III., "Additional Information" applies only to <u>large mining operations</u> .
III. <u>Additio</u>	onal Information - R647-4-121.2 and .3
1.	The operator shall include an updated map depicting surface disturbance and reclamation performed during the year, prepared in accordance with Rule R647-4-105.
2.	The operator shall keep and maintain timely records relating to his performance under the Act, and shall make these records available to the Division upon request.
IV. <u>Signa</u>	ture Requirement
11	hereby certify that the foregoing is true and correct.
	Name (Typed or Print): GREGORY M. Foy
	Title of Operator: PLANT MANAGER
	Signature of Operator:
	Date: 01/10/02
76	——————————————————————————————————————
jb o:\forms\reports	NMR-AR

RECEIVED

JAN 14 2002